

Changes to the fourth edition following September 2016 update

Section Page Amendment

Introduction

Table 1	3	New Robust Detail separating wall E-WM-30 added.
Table 3a	6	New Robust Detail separating wall E-WM-30 added with valid combinations.
Table 4	8	New Robust Detail separating wall E-WM-30 added with relevant notes.
Table 6a	9	New Robust Detail separating wall E-WM-30 added with valid combinations.

Separating Wall – Masonry

E-WM-30

All	1-6	New Robust Detail separating wall added – Aircrete blockwork Knauf Party Wall Wool (gypsum-based board) with 100mm minimum cavity.
-----	-----	------------------------------------------------------------------------------------------------------------------------------------

Separating Floor – Timber

E-FT-5

Isometric	1	Second ceiling removed from illustration.
Sections 1-4	2-3	Second ceiling removed from illustrations; resilient bars replaced with HP30 bars.
Section 5	4	Page reformatted to include new ceiling option CT3.
Sections 6-7	5	Second ceiling removed from illustrations; resilient bars replaced with HP30 bars.
Checklist	6	Notes added relating to new ceiling option CT3.

E-FT-6

Isometric	1	Second ceiling removed from illustration.
Sections 1-8	2-5	Second ceiling removed from illustrations; resilient bars replaced with HP30 bars.
Section 9	6	Page reformatted to include new ceiling option CT3.
Sections 10-11	7	Second ceiling removed from illustrations; resilient bars replaced with HP30 bars.
Checklist	8	Notes added relating to new ceiling option CT3.