Changes to the fourth edition following March 2020 update

Section	Page	Amendment	Section	Page	Amendment	
Introduct		Separating Floor – Timber				
Table 2	5	New floor type, E-FC-19 added.	E-FT-1			
Table 3a	6	New floor type, E-FC-19 added with valid combinations.	Floating floor treatments	5	FFT2 cradle systems added as an option.	
Table 5	8	New floor type, E-FC-19 added with relevant note.	Services through floor	6	Section 7 moved from previous page.	
Table 6b	11	New floor type, E-FC-19 added with valid combinations.	E-FT-3			
Table 7	12	New floor type, E-FC-19 added with valid combinations.	Floating floor treatments	7	FFT2 cradle systems added as an option.	
Separatin	all – Masonry	Services through floor	8	Section 11 moved from previous page.		
E-WM- 8			E-FT-5			
All	1	Asterisks and footnote added	Isometric	1	Minimum joist depth amended.	
		advising RD35 no longer manufactured.	Ceiling treatments	4	CT3 applicable only to minimum 204mm joists.	
E-WM-14	ı		Checklist	6	Points 1 and 6 amended to reflect the	
All	1	Asterisks and footnote added advising RD35 no longer manufactured.	Appendix A2		above.	
E-WM-15	ı		Roofspace I-Roof	7	Diagram added showing how to form the head detail in a stepped	
All	1	Asterisks and footnote added			terrace.	
		advising RD35 no longer manufactured.			Gypsum board weights added under item j.	
E-WM-31						
Diagram 8	6	Diagram added showing how to form the head detail in a stepped terrace.				
All	1-8	Pages renumbered.				
Separatin	a Fla	oor – Concrete				
F-FC-18	· ·					

E-FC-18

Under-screed resilient layers	1	Cellecta RUBBERfon® Impact 6 system added as an option.
Resilient layer system box	5	Cellecta RUBBERfon® Impact 6 added as an option.

E-FC-19

NI 1-6 New Robust Detail added – Cellecta RUBBERfon® Impact 6 system and floating screed.